ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0872, W0864, W0870, W1151, W1147, W0868, W1145, W	NA	veerannapalya
Segment No.	**Total Length (m)**	
7/S-W0872/S114453	558.62	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	102.06	77.610621	13.040911	77.611549	13.040758	veerannapalya Main Road	Dead End
2	223.26	77.609069	13.040174	77.611069	13.039725	veerannapalya Main Road	Dead End
3	173.43	77.609403	13.039872	77.610975	13.039583	veerannapalya Main Road	Dead End
4	59.87	77.610047	13.039079	77.610590	13.038981	veerannapalya Main Road	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drains of veerannapalya in ward no.07 Byataranapura.	7500000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	1.Construcyion of RCC Drains (left side only for road id W0870)2.Providing and laying RCC Covering Slabs.	007-20-000005
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/138/19-20	08/11/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
03/03/2020	02/03/2022	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Executive Engineer, K.R.I.D.L		0.00

Scanned by CamScanner

Phone No.	E-Mail ID
9900333496	

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Pushpalatha.N.D
Date of Inspection	**Remarks**	
03/03/2020		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0872, W0864, W0870, W1151,

Pushpalatha.N.D
AE(W7)

Assistant Executive Engineer
Kodigehalli Sub Division
Bruhat Bangalore Mahanagara Palike
Bangalore - 560 092

Scanned by CamScanner